

Quality and Utility Assessment of Completed EPA's

District: Baghalpur Project Title: Baghalpur -WDC-I /2021-22

Block: Kahulgaon Panchayat: Mathurapur Village: Jagamtasan Beneficiary Name: Gopal u Raon

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18637	Structure: <u>Chabutra</u>	<u>25.297764</u> <u>87.341128</u>	<u>100%.</u>	<u>100%.</u>	<u>100%.</u>	<u>100%.</u>	<u>100%.</u>	<u>100%.</u>

Remark (Overall Quality & Utility of Structure):

कार्य रखरखाव एवं कार्य की गुणवत्ता दी गई है - जो कि ग्रामिणी द्वारा चबुत्रा का उपयोग भजन करने में किया जाता है - तथा जागवरी का - चारा रखने सुरवाते में उपयोग किया जाता है । तथा मौजना का - बौड़ लगा हुआ है ।

Visit Date:- 14-3-2024

Name:- Koshalkumar DEO

Signature:- Koshal Kumar DEO