

Quality and Utility Assessment of Completed EPA's

District: Bhopur

Project Title: Bhopur

-WDC- I/2021-22

Block: Koi/war

Panchayat: Kayamngar

Village: Kayamngar

Beneficiary Name: Rama Shankar Shah

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4519	Structure: <u>Chabutra</u> <u>Mangapump</u>	<u>25° 35' 28"</u> <u>84° 43' 24"</u>	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्गि स्थल का चयन स्व कार्य कि गुणवत्ता अच्छी है। जो जामिनी द्वारा
पापकल का उपयोग करने है। पापकल पर हि डिस्पल कोड पाया गया है।
जिसमें पुरा विकरण आंकित है। आस-पास के बटवानी ले जाना और
पिना - स्थान कारना और कपडा चमका है।

Visit Date:- 10/10/2021/ (7:53)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh