Quality and Utility Assessment of Completed EPA's

District: Bhoper

Project Title: Bhojpu

-WDC- f /2021-22

Block: Koilwar Panchayat: Khangaon Village: Khangaon

Beneficiary Name: pawan kumar singh

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
1	Structure: Handpump	25.515374 84.752353	1 0 07.	loo9.	100%.	100-)	100%	1007
		0, 10, 30,						ĺ

कार्य देशल का न्यम प्रव कार्य कि ग्रुपम्ला अर्दिश भी आंत- पात के ज्योमिणी द्वारा नापानल कार्यहरूपयोग कर्रिश भी कि न्यापानल पर हि

Visit Date: 09-10-23 (7. 40)

Name: - Arnit Kumar Sign

Signature: Amid-Kumar Sign