

Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC- III/2021-22

Block: Chandan Panchayat: Koriya Village: Head Chandan Beneficiary Name: Gujari Devi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18822	Structure: Renovation of Well	24.610341 86.715535	100%	100%	100%	80%	100%	96%

Remark (Overall Quality & Utility of Structure):

कार्य-पटल का चयन रखे कार्य की गुणवत्ता अच्छी है।
जो कि ग्रामिणों द्वारा कुआर का उपयोग किया जाता है।
कुआर पद पालना विवरण लिखा हुआ है।

Visit Date:- 20/12/23

Name:- Brindaban Mahato

Signature:- Brindaban Mahato