

Quality and Utility Assessment of Completed EPA's

District: ARWAH Project Title: ARWAH -WDC-1 /2021-22

Block: BANSHI Panchayat: MALI Village: MALI Beneficiary Name: ALOK KUMAR

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17756	Structure: HAND PUMP	25.126255 84.700831	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कमल का चमक एवं कर्म की गुणवत्ता अच्छी है, जो कि
ग्रामों के अनुसार हैंडपंप का उपयोग उनके द्वारा किया
जाता है एवं उनके लिए लाभप्रद कर्म है, स्थल पर पर
डिस्पले बोर्ड वही काम गम।

Visit Date:- 06/12/23

Name:- ADRAJKUMAR

Signature:- Alok Kumar