

Quality and Utility Assessment of Completed EPA's

District: Banka

Project Title: BANKA

-WDC- 1 /2021-22

Block: Katoriya

Panchayat: Kelhasar

Village: Barakala

Beneficiary Name: Giridhari Kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18671	Structure: Chabutra	24.644983 86.869344	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्पसुशल का चयन एवं कार्य की गुणवत्ता अच्छी है, जो की
ग्रामिणों के अनुसूचित चक्रवात का निमण उभरे लिए उपयोग
है, चक्रवात पद योजना विवरण लिखा हुआ पाया गया;

Visit Date:- 13/12/23

Name:- Brindaban Mahto

Signature:- Brindaban