

Quality and Utility Assessment of Completed EPA's

District: Bhopur Project Title: Bhopur -WDC-I /2021-22

Block: ara Sadar Panchayat: Bhakura Village: Bhakura Beneficiary Name: maiti devi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4529	Structure: Chabutra	25.6196 25 84.701317	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्गि सुधल शव कार्गि की गुणवत्ता ठीक है। जो आगिणी द्वारा चकुतरा उपलोग किया जा रहा है। शव डिस्पल कर्डि पाया गया है।
किसानी की वहुतही राहत है चरा-सुखाना सुकट रशाहा बँक ना

Visit Date:- 09/10/2023

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh