

Quality and Utility Assessment of Completed EPA's

District: Baghalpur Project Title: Baghalpur-WDC-I/2021-22

Block: Kaihalgaon Panchayat: Bidhanna Village: Kutiola Beneficiary Name: Kajal Kumari

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18658	Structure: Chabutra	25.350527 87.310304	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य-स्थल एवं कार्य-की-सुव्यवस्था ठीक है। जो कि ग्रामीणों द्वारा-
फलदायक कार्य-कारण स्तर से ला उत्तर-दक्षिण-हीन-कने-
का-काम में उपयोग-किया-जाता-है ,
भीषणा का बॉर्डर लगा हुआ है ,

Visit Date:- 14-3-2024

Name:- Koshal Kumar Jato Signature:- Koshal Kumar Jato