

Quality and Utility Assessment of Completed EPA's

District: Bhopur

Project Title: Bhopur

-WDC-I /2021-22

Block: Koilwar

Panchayat: Narbirpur Village: Chandli

Beneficiary Name: Ash Kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4527	Structure: Chabutra	25.535891 84.747859	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्गि स्थल एवं कार्गि की गुणवत्ता ठीक है जो कि गन्मिणी द्वारा
चक्रुतरा का उपयोग किया जा रहा है और डिस्पल के
पाया गया है। अगल में स्कूल के है जो कि कार्य- चक्रुतरा पर रकेल है।

Visit Date:- 09/10/23 (13:09)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh