

Quality and Utility Assessment of Completed EPA's

District: **BANKA** Project Title: **BANKA** -WDC- I /2021-22

Block: **Kodariya** Panchayat: **Lakrama** Village: **Chayehappa** Beneficiary Name: **Rahul Soren**

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18680	Structure: Chabutra	24.620596	100%	100%	100%	100%	100%	100%
		86.87612						

Remark (Overall Quality & Utility of Structure):

कार्पस्थल का चयन एवं कार्य की गुणवत्ता अच्छी है, जो कि ग्रामियों द्वारा चबुतरा का उपयोग किया जाता है। चबुतरा पर योजना विवरण लिखा हुआ है।

Visit Date:- 14/12/23

Name:- Brindaban Mahto

Signature:- Brindaban