

Quality and Utility Assessment of Completed EPA's

District: **BANKA** Project Title: **BANKA** -WDC- **I** /2021-22

Block: **Kataruiya** Panchayat: **Kalhasan** Village: **Jhilki** Beneficiary Name: **Buddu Soren**

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18688	Structure: Chabutra	24.637443 86.888899	100%	100%	100%	60%	80%	88%

Remark (Overall Quality & Utility of Structure):

कार्पस्थल का चयन एवं कार्य की गुणवत्ता ठीक है, जो कि
ग्रामिणों द्वारा उपयोग किया जाता है, चबुतरा किनाड़े पर उपर
से बरसता एवं हटा हुआ पाया गया,

Visit Date:- **13/12/23**

Name:- **Birendaban Mahato**

Signature:- **Birendaban**