

Quality and Utility Assessment of Completed EPA's

District: BANKA **Project Title:** BANKA -WDC- I /2021-22

Block: Katoriya **Panchayat:** Lakrama **Village:** Narayanpur **Beneficiary Name:** Dilip Kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18690	Structure: <u>Uhalutra</u>	<u>24.607664</u>	100%	100%	100%	100%	100%	100%
		<u>86.908466</u>						

Remark (Overall Quality & Utility of Structure):

कारि-यल लर पयन शव कारि की गुणवत्ता उत्तम है, लर
लि गुणवत्ता के अनुसार - वलुता लर निमलि उत्तम है
उपयोगी है, - वलुता पद योजना विवद, लिता उत्तम है

Visit Date:- 17/12/23

Name:- Brindaban Mahato

Signature:- Brindaban