

Quality and Utility Assessment of Completed EPA's

District: BANKA **Project Title:** BANKA -WDC- I /2021-22

Block: Katoriya **Panchayat:** Lakrama **Village:** Kurwar **Beneficiary Name:** Arvind Yadav

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18678	Structure: Chabutra	24.629137 86.915747	100%.	100%.	100%.	100%.	100%.	100%.

Remark (Overall Quality & Utility of Structure):

कारिखल का चबूतरा एवं कारि की गुणवत्ता अच्छी है, जो कि समिती के अनुसार चबूतरा का निर्माण उनके लिए उपयोगी है।

Visit Date:- 14/12/2023

Name:- Brindaban Mahato

Signature:- Brindaban