

Quality and Utility Assessment of Completed EPA's

District: Baghalpur Project Title: Baghalpur -WDC-I /2021-22

Block: Kahaugoon Panchayat: Kishanjaspur Village: Kishanjaspur Beneficiary Name: Jaynath Yadav

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18640	Structure: Chhatra	25.333295 87.333674	100%.	100%.	100%.	80%.	80%.	92%.

Remark (Overall Quality & Utility of Structure):

कार्य स्थल पर कार्य की गुणवत्ता ठीक हो गई है कि कमीती द्वारा
चबुरा का उपयोग हुआ पाठ तथा निधि कार्य करके कार्य -भारत ला पत्रिका
पुरवानी का उपयोग में लाने हो ।
ये ईस्ट्रुक्चर में बस गयी लगा है-

Visit Date:- 14-3-2024

Name:- Koshal Kumar

Signature:- Koshal Kumar