

Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC-II /2021-22

Block: Katoriya Panchayat: Damodara Village: Burighat Beneficiary Name: Matra Tudu

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18860	Structure: Renovation of Well	24.724056 86.802128	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्पस्थल का चयन एवं कार्य की गुणवत्ता अच्छी है, जो कि ग्रामियों के 3-4 फुट ऊँचाई का और नीला रंग, उनके लिए उपयोगी है, ऊँचाई का पद योजना विवेक से लिया हुआ है,

Visit Date:- 11/12/23

Name:- Brindaban Mahto

Signature:- Brindaban