

Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC- I /2021-22

Block: Katoriya Panchayat: Lakrama Village: Sahdeva Nawadih Beneficiary Name: Sanjhali Hadda

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18668	Structure: Chabutra	24.597333 86.874628	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य-शाला का चयन एवं कार्य की गुणवत्ता अच्छी है। गाँव
ग्रामिणों के अनुसार चबूतरा का निर्माण उमरें लिये
उपयोगी है। चबूतरा पर योजना विवरण लिखा हुआ है।

Visit Date:- 14/12/2023

Name:- Brindaban Mahato

Signature:- Brindaban