

Quality and Utility Assessment of Completed EPA's

District: BANKA **Project Title:** BANKA -WDC- I /2021-22

Block: Katoriya **Panchayat:** Lakrama **Village:** Titlakho **Beneficiary Name:** Rita Devi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18691	Structure: Chabutra	24.634807 86.865896	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्प-रथल का चपरा एवं चपरा की गुणवत्ता अच्छी है। जो कि चबुतरा का उपयोग ग्रामिणों द्वारा बैठने एवं भाजन विहिन में लिया जाता है, चबुतरा बि मंदिर के बगल में है, चबुतरा पर योजना विवरण लिखा हुआ है।

Visit Date:- 14/12/23

Name:- Bindaban Mahato

Signature:- Bindaban