

Quality and Utility Assessment of Completed EPA's

(12)

District: Begusarai Project Title: Begusarai -WDC- I /2021-22

Block: Bispur

Panchayat: Parra

Village: Parra

Beneficiary Name: Rahul kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
459	Structure: Construction of Soak Pit	25.492417 86.095441	100	80%	100%	80%	100%	92%

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का चयन स्व गुणवत्ता शीक है। ग्रामीणों के उपयोग में है। शाक पीट के कादरी दिखा
लगाकर नहीं है। स्व चापाकल और शाक पीट की थोड़ी दूरी है सड़क के एक तरफ चापाकल
स्व दूसरी तरफ शाक पीट है। दोनों के साथ होल लोडिंग जिसके कारण हम फौरन में दोनों एक
नहीं दिखा सकते हैं। क्योंकि शाक पीट के पास कोई चापाकल है। जिससे कोई लगा है जिसपर
विवरण डालिए है।

Visit Date:- 08-12-2023

Name:- Umesh Yadav

Signature:- Umesh Yadav