

Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: PMKSY 20 -WDC- I/2021-22

Block: Deo

,Panchayat: Dulare

,Village: Golha

,Beneficiary Name: Dhananjay kumar Yadav

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18953	Structure: Chabutra	24.542018	100 %.	100 %.	100 %.	100 %.	100 %.	100
		84.349852						

Remark (Overall Quality & Utility of Structure):

Structure की गुणवत्ता अच्छी है, लोग द्वारा सामुहिक कार्य में उपयोग में है।
चबूतरा में display board नहीं लगा हुआ है।

visit Date: - 15.10.23

Name:- Shishupal

sign:- Shishupal