

Quality and Utility Assessment of Completed EPA's

District: Baghalpur Project Title: Baghalpur -WDC-I /2021-22

Block: Kachhalgaon Panchayat: Rampur

Village: Jati Pura

Beneficiary Name: Sakran Kumar Sinha

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18657	Structure: Chabutra	25.28 06 71 87.29 81 57	100 %	100 %	100 %	100 %	100 %	100 %

Remark (Overall Quality & Utility of Structure):

कार्य-स्थल एवं सुगमता सेक है-जी-कि-आमीनी-हाल-चबुतरा पर फलहन
का-फलन आकर वन-यल-सुरगरी-पीलाने-का-तथा-मर्फी-का-
यल-सर्वे-का-उपयोग-करते है।

भीषना का-कोई लगा हुआ है,

Visit Date:- 16-4-2024

Name:- Koshal Kumar Rao

Signature:- Koshal Kumar Rao

9