

Quality and Utility Assessment of Completed EPA's

District: BANKA **Project Title:** BANKA -WDC- II /2021-22

Block: Katoriya **Panchayat:** Damodarata **Village:** Kamdevdih **Beneficiary Name:** Parmod Kumar Yadav

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18869	Structure: Renovation of Bandh	24.727778 86.780833	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्पस्थल का चयन एवं कार्य की गुणवत्ता ठीक है, जो कि ग्रामिणों द्वारा बताया कि बाँध का उपयोग सिंचाई आदि में लिया जाता है, स्थल पर डिस्पले बोर्ड पाया गया।

Visit Date:- 21/05/24

Name:- Brindaban Mahato

Signature:- Brindaban