## Quality and Utility Assessment of Completed EPA's

District: Aurangabad, Project Title: PMKSY2.0 -WDC- I/2021-22

Panchayat: Dumri Block: Kutumba

, Village: Joda , Beneficiary Name: Suresh Paswan

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
05681	Structure: Hand tubewell with Soak Pit	24.581214	( 00 Y.	100%	1001/	100 %	100%	100

Remark (Overall Quality & Utility of Structure):

Structure की गुठावला अरकी है, लामाबी द्वारा उपयोग में है। structure के पास वाक्षीया board नहीं पाया गया।

Visit Date: - 06.10.23

Name: - shishupal

Sign: - Shishupal