

Quality and Utility Assessment of Completed EPA's

14

District: Begusarai Project Title: Begusarai -WDC- I/2021-22

Block: Bixpur Panchayat: Genharpur Village: Genharpur Beneficiary Name: Raushan kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
19288	Structure: Construction of Soak pit	25.511924 86.040683						

Remark (Overall Quality & Utility of Structure):

कार्य स्थल पर मुझे शाक पीट का बना हुआ नहीं मिला केवल वहां पर मुझे एक चापाकल मिला वहां के पंचायत सेवीव के द्वारा मुझे जानकारी दी गई कि शाक पीट के ऊपर ही चबुतरा बना दिया गया है। कोई डिस्पले बोर्ड भी मुझे नहीं मिला।

Visit Date:- 08-12-2023

Name:- Umesh Yadav

Signature:- [Signature]