

Quality and Utility Assessment of Completed EPA's

District: Baghelpur Project Title: Baghelpur -WDC-I/2021-22

Block: Kahalgaon Panchayat: Rampur Village: Jatipur Beneficiary Name: Bixhu Devi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18659	Structure: Laddy Bathroom	25.293701 87309558	100 %	100 %	100 %	80 %	0 %	76 %

Remark (Overall Quality & Utility of Structure):

कार्म रकम एम कार्म की - गुणवत्ता छीक है -
 ग्रामीणों द्वारा इसका उपयोग नहीं हो रहा है इन लोगों ने बताया कि
 पानी के अभाव के कारण उपयोग - नहीं हो रहा है।

आजना डा - बर्ड लगा हुआ है -

Visit Date:- 14-3-2024

Name:- Koshal Kumar Deo

Signature:- Koshal Kumar Deo