Quality and Utility Assessment of Completed EPA's

District: Aurangabad, Project Title: PMKSY 20 -WDC-11/2021-22

Block: Alabinagar, Panchayat: Basdina, Village: Sonsagar, Beneficiary Name: Bishwanath kumar Mehta

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
	Structure: Hand Tube well with Soak Pit	24.545442	100%	100 %	100%	100%	100%	100

Remark (Overall Quality & Utility of Structure):

Structure की गुठावता अच्छी है, लाभाशी द्वारा उपयोग में है। Display board

Visit Date: - 13.10.23

Name: - Shishupal

sign: - shishupal.