

Quality and Utility Assessment of Completed EPA's

District: Bhojpur

Project Title: Bhojpur

-WDC- II /2021-22

Block: Arq Sadar

Panchayat: Makhdumpur

Village: Shobhiduma

Beneficiary Name: Vir Kumar Singh

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4481	Structure: Hand pump	25.58944 84.659027	100%.	100%.	100%.	100%.	100%.	100%.

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का चयन एवं कार्य कि गुणवत्ता अच्छी है जो
आस-पास के ज़ामिनी द्वारा चापाकल का उपयोग करते हैं। जो
चापाकल पर हि डिस्पलर्ड कांड अंगित है।

Visit Date:- 07/10/2022 (09:22)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh