

Quality and Utility Assessment of Completed EPA's

District: Bhojpur

Project Title: Bhojpur

-WDC-fj /2021-22

Block: Am Sadar

Panchayat: Khajuriya

Village: Khajuriya

Beneficiary Name: Dhanoj Kumar paswan

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4496	Structure: Hand pump	25.586328 84.568962	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का पर्यवेक्षण कर कार्य कि गुणवत्ता अच्छी है जो आस-पास के ग्रामीणों के द्वारा व्यापक रूप से पानी-पैनी एवं बरत में उपयोग करते हैं। डिस्पलर कोडिंग व्यापक पर अंकित थी। वहीं का ग्रामीण व्यापक पर पेंट कर दिया है यह स्पष्ट नहीं कि जा रहा है कि डिस्पलर कोडिंग है या नहीं।

Visit Date:- 10-10-2023 (15:13)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh