

Quality and Utility Assessment of Completed EPA's

District: BHOPUR

Project Title: Bhopur

-WDC-I /2021-22

Block: Agra Sadar

Panchayat: Gautha 19

Village: Barwadi

Beneficiary Name:

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4532	Structure: Chabutra	25.526798	100%	100%	100%	100%	100%	99%
		84.70281						

Remark (Overall Quality & Utility of Structure):

कार्य स्थल एवं कार्य की गुणवत्ता अच्छी है। जो चबुतरा बना है फंड के नियम है चबुतरा पर किसान बैठा आराम करना तथा जानवरों चारा रखना सुरक्षा में उपयोग करते हैं। ग्रामीणों के द्वारा देख रखा होने कारण कोई जगह नहीं देखा है। चबुतरा के निर्माण डिस्पल करे आंगिरा है।

Visit Date:- 08-10-23 (10:57)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh