

Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: PMKSY 2.0 -WDC- II/2021-22

Block: Deo

,Panchayat: Bedhna

,Village: Barheta

,Beneficiary Name: Rambravesh Ram

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18977	Structure:	24.585507	100 %	100 %	100 %	100 %	100 %	100
	chabutra	84.42808						

Remark (Overall Quality & Utility of Structure):

Structure की गुणवत्ता अच्छी है, लोग द्वारा सामाजिक कार्य हेतु उपयोग में है।
चबूतरे में display board लगा हुआ है।

Visit Date: - 29.09.23

Name: - Shishupal

Sign: - Shishupal