

### Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: PmkSY 2.0 -WDC- II/2021-22

Block: madanpur , Panchayat: South Umga , Village: sahiyari tola, Dhak Park , Beneficiary Name: Lalji Bhuiyan

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
696	Structure: Hand tubewell with soak pit	24.525000	100 %	100 %	100 %	100 %	100 %	100
		84.478889						

**Remark** (Overall Quality & Utility of Structure):

structure की गुणवत्ता अच्छी है, लाभार्थी द्वारा उपयोग में है। structure के पास display board लगा हुआ है।

visit Date:- 15.10.23

Name:- Shishupal

Sign:- Shishupal