

# Quality and Utility Assessment of Completed EPA's

District: Baghalpur Project Title: Baghalpur-WDC-I /2021-22

Block: Kahalgaon Panchayat: Rampur Village: Jiti pur Beneficiary Name: Kailu Pantit

| Work ID | Name/ description of activity      | Latitude & Longitude   | Work Identification<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Site Identification<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Specification<br>Followed<br>(Totally 100%,<br>Mostly 80%,<br>Average 60%,<br>Poor 40%) | Physical Appearance<br>of Structure<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Utility of Structure<br>(In full use 100%,<br>partially used 80%,<br>Yet to be used 70%,<br>Occasionally used 60%,<br>Not used/rarely used 40%) | Average<br>Score |
|---------|------------------------------------|------------------------|---|---|---|---|---|------------------|
| 1       | 2                                  | 3                      | 4   | 5   | 6   | 7   | 8   | 9                |
| 18655   | Structure:<br>Hand PUMP<br>+ SOKTA | 25.292819<br>87.310952 | 100%.   | 100%.   | 100%.   | 86%.  | 0 %.  | 76%.             |

Remark (Overall Quality & Utility of Structure):

कार्य-रूप का - यमन खीड़ है लेकिन कार्य-गुणवत्ता हीट नहीं है  
हैंड पम्प में पानी नहीं आता है- हैंड पम्प - खराब है. जिसके कारण -  
ग्रामीणों द्वारा इसका उपयोग नहीं है / तथा ये इंस्ट्रुमेंट का -  
खर्च नहीं लगा है.

Visit Date:- 19-4-2024

Name:- Ko Shal Kumar

Signature:- Ko Shal Kumar