

Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: Pmksy 2.0 -WDC-II/2021-22

Block: Deo , Panchayat: Bedhna , Village: Karamdih , Beneficiary Name: Parikshan Ram

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18972	Structure: Hand Tubewell with soak pit	24.599436 84.420793	100%	100%	100%	100%	100%	100

Remark (Overall Quality & Utility of Structure):

Structure की संरचना और कार्यप्रणाली में, सामग्री की उपयोगिता और रखरखाव में।
Display board का स्थान और।

Visit Date :- 01-06-2024

Name :- Shishupal

sign:- Shishupal