

Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: PMKSY 2.0 -WDC- II/2021-22

Block: Deo

,Panchayat: Eroua

,Village: Eroua Tola, Bhandari Beneficiary Name: Prabhat Kumar Ranjan

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18976	Structure: Chabutra	24.583368 84.447776	100 %	100 %	100 %	100 %	80 %	96

Remark (Overall Quality & Utility of Structure):

कार्यस्थल एवं structure की गुणवत्ता अच्छी है, लोगो द्वारा सामाजिक कार्य के लिए उपयोग में है। चबुत्रे में display board नहीं लगा हुआ है। देखने से प्रतीत होता है की display board लगाया गया था पर किसी ने निकाल दिया है।

visit Date:- 15.10.23

Name:- Shishupal

Sign:- Shishupal