

Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: PMKSY 2.0 -WDC- II/2021-22

Block: Madanpur , Panchayat: South umga , Village: Sahiyari , Beneficiary Name: Baudh Bhuian

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18978	Structure: <u>chabutra</u>	<u>24.523893</u>	<u>100%</u>	<u>100%</u>	<u>100%</u>	<u>80%</u>	<u>100%</u>	<u>96</u>
		<u>84.480267</u>						

Remark (Overall Quality & Utility of Structure):

Structure की गुणवत्ता अच्छी है, लोगों द्वारा सामाजिक कार्य हेतु उपयोग में है।
यहाँ से display board भी लगा हुआ है।

visit Date:- 15.10.23

Name:- Shishupal

Sign:- Shishupal