

Quality and Utility Assessment of Completed EPA's

District: ARWAH Project Title: ARWAH -WDC- I /2021-22

Block: BANSHI Panchayat: CHAMANDI Village: CHAMANDI Beneficiary Name: DHANJAY SHARMA

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
12750	Structure: construction of Chabutra	25.120387 84.76836	100%.	100%.	100%.	100%.	100%.	100%.

Remark (Overall Quality & Utility of Structure):

कमल चबुतरा का चबुतरा एवं गुणवत्ता ही है, जो कि चबुतरा मंदिर के बगल में बना हुआ है, लोग वहीं पूजा करने आते हैं, तो वहीं बैठते हैं, और चबुतरा का उपयोग भजन किर्तन में भी उपयोग किया जाता है, स्थल पर स्थित कोई भी नाम नहीं।

Visit Date:- 11/12/23

Name:- ADRAJ KUMAR

Signature:- Adraj Kumar