

(4)

Quality and Utility Assessment of Completed EPA's

District: Begusarai Project Title: Begusarai -WDC- I /2021-22

Block: Barauni Panchayat: Bhabhangama Village: Bhabhangama Beneficiary Name: Ranjan Kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
551	Structure: Construction of chabutra	25.482183 86.120942	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का चयन एवं कार्य की गुणवत्ता अच्छी है। चबुतरा स्कूल में बना है।
स्कूल के बच्चों के उपयोग में है। चबुतरा पर डिस्पले बोर्ड लगाया गया जिस पर पुरा
चित्रण अंकित था।

Visit Date:- 08-12-2023

Name:- Umesh Yadav

Signature:- UYAD