

Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: PMKSY 2.0 -WDC- II/2021-22

Block: Deo

, Panchayat: Eroua

, Village: Eroua Tola @ Chandar

Beneficiary Name: Shekhar kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18961	Structure: Hand tubewell	24.583258	100 %	100 %	100%	100 %	100 %	100
	With Soak Pit	84.44783						

Remark (Overall Quality & Utility of Structure):

Structure की गुणवत्ता अच्छी है, लाभकारी द्वारा उपयोग में है।
Display Board नहीं लगाया गया।

Visit Date:- 15.10.23

Name:- Shishupal

Sign:- Shishupal