

Quality and Utility Assessment of Completed EPA's

District: ARWAL Project Title: ARWAL -WDC-1/2021-22

Block: BANSAL Panchayat: KHARASIN Village: PAHARPUR Beneficiary Name: RAMNIWASH SHARMA

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17774	Structure: HAND PUMP	25.103239 84.667274	100%	100%	100%	100%	100%	100%
Remark (Overall Quality & Utility of Structure): कोमल बचल का चमक एवं गुणवत्ता हीक है, ग्रामियों के कुतुहल है। पम्प का उपयोग कम होता है, बचल पर पर डिस्पले बोर्ड नहीं पाया गया।								
Visit Date:- 05/12/23			Name:- NIRAJ KUMAR			Signature:- Niraj Kumar		