

### Quality and Utility Assessment of Completed EPA's

District: Aurangabad, Project Title: PMKSY 2.0 -WDC- III 2021-22

Block: Nabinagar ,Panchayat: Khajuri Pandu ,Village: Khajuri Pandu ,Beneficiary Name: Bhagwati Singh

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18931	Structure: Hand Tubewell with Soak Pit	24.509353 84.123961	100 %	100 %	100 %	100 %	100 %	100

**Remark** (Overall Quality & Utility of Structure):

Structure की गुणवत्ता अच्छी है, लाभार्थी द्वारा उपयोग में है। Structure के पास display board लगा हुआ है।

Visit Date:- 13.10.23

Name:- Shishupal

Sign:- Shishupal