

Quality and Utility Assessment of Completed EPA's

8

District: Begusarai Project Title: Begusarai -WDC-I/2021-22

Block: BIRPUR

Panchayat: Parra

Village: Sarauja

Beneficiary Name: Nakul Sah

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
455	Structure: Construction of chabutra	25.509592 86.110011	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का-पयन रूप गुणवत्ता अच्छा है। ग्रामीणों के उपयोग में है। ग्रामीण अपने
हाल-हाल काम के लिए-चबुतरा का उपयोग करते हैं। चबुतरा पर डिस्पले बोर्ड
नहीं लगा है।

Visit Date:- 08-12-2023

Name:- Umesh Yadav

Signature:- Umesh Yadav