

Quality and Utility Assessment of Completed EPA's

5

District: Begusarai Project Title: Begusarai -WDC-I /2021-22

Block: Barauni

Panchayat: Sahur

Village: Sahur

Beneficiary Name: Vinay Kumar Singh

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
452	Structure: Construction of chabutra	25.478201 86.083098	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का चयन एवं गुणवत्ता अच्छी है। चबुतरा स्कूल के प्रांगण में बना है। स्कूल के बच्चों के उपयोग में है। आम लोग के उपयोग में नहीं है। क्योंकि स्कूल छुट्टी के बाद स्कूल का गेट बन्द हो जाता है। जिसके कारण आम लोग के उपयोग नहीं कर सकते। चबुतरा में डिस्पले कोई पाया गया जिसपर विवरण डाला था।

Visit Date:- 08-12-2023

Name:- Umesh Yadav

Signature:- 