

Quality and Utility Assessment of Completed EPA's

District: Bhojpur Project Title: Bhojpur -WDC- I /2021-22

Block: Am Sader Panchayat: Gauthaul Village: Shusaul Beneficiary Name: Pradeep Kumar Singh

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
44-99	Structure: <u>Renovation</u> <u>well</u>	<u>25.533208</u> <u>84.686524</u>	<u>100%</u>	<u>100%</u>	<u>100%</u>	<u>100%</u>	<u>100%</u>	<u>100%</u>

Remark (Overall Quality & Utility of Structure):

कार्य स्थल एवं कार्य की गुणवत्ता ठीक है, जो ग्रामीणों द्वारा कुआ
का उपयोग किया जा रहा है। एवं डिस्पलॉय का भी काम किया जा रहा है।
ग्रामीणों द्वारा कुआ की देख रेख नहीं किया जा रहा है।

Visit Date:- 08/10/2023 (10:41)

Name:- Amrit Kumar Singh

Signature:- Amrit Kumar Singh