

Quality and Utility Assessment of Completed EPA's

District: Bhojpur

Project Title: Bhojpur

-WDC- 1 /2021-22

Block: Udwantnagar Panchayat: Bakri

Village: Kharjhad

Beneficiary Name: Ram Laddu Singh

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4523	Structure: Chabutra	25.521808 84.661995	100%	100%	100%	100%	100%	100%
Remark (Overall Quality & Utility of Structure): कार्य स्थल एवं कार्य की गुणवत्ता उत्तम है। जो आगिरा द्वारा चकुरा का उपयोग किया जा रहा है। एवं डिस्मैंट ऑफ बाधा गया है।								
Visit Date:- 27/09/2023/ (12:40)			Name:- Amit Kumar Singh			Signature:- Amit Kumar Singh		