

Quality and Utility Assessment of Completed EPA's

District: ARWAAL Project Title: ARWAAL -WDC- I /2021-22

Block: BANSHI Panchayat: SONBHADRA Village: BANSHI Beneficiary Name: VISHNO MISRA

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17763	Structure: Renovation of Well	25.114312 84.721158	100%.	100%	100%	100%	100%	100%
Remark (Overall Quality & Utility of Structure): स्थलपट्ट में चमक एवं गुणवत्ता ठीक है, जो कि ग्रामिणों के अनुसार उनकी भी उपयोग क्षेत्र की लिचार्ज के लिए उपयोग किया जाता है, कता मह काम लाभप्रद है, स्थल पट्ट पर डिप्लेस कीड पाया गया।								
Visit Date:- 11/12/23			Name:- NIRAJ KUMAR			Signature:- Niraj Kumar		