

Quality and Utility Assessment of Completed EPA's

District: ARWAH Project Title: ARWAH -WDC-I/2021-22

Block: BANSHI Panchayat: CHAMANDI Village: DHARAMPUR Beneficiary Name: SANJAY SINGH

| Work ID | Name/ description of activity | Latitude & Longitude | Work Identification (Excellent 100%, good 80%, average 60%, poor 40%) | Site Identification (Excellent 100%, good 80%, average 60%, poor 40%) | Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%) | Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%) | Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%) | Average Score |
|---------|-------------------------------|------------------------|---|---|---|---|---|------------------|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
| 17780 | Structure: HAND PUMP | 25.110688 84.762375 | 100% | 100% | 100% | 60% | 100% | 92% |

Remark (Overall Quality & Utility of Structure):

कम स्थल का चयन ठीक है, लेकिन गुणवत्ता खराब है; हैंडपंप का कार्य नहीं बना हुआ है। हैंडपंप गाँव के ठीक बिच में बना हुआ है। कता ग्रामियों के अनुसार उपयोग किया जाता है। यह कम लाभप्रद है, लेकिन स्थल पट्ट पर बिस्पले बॉर्डर नहीं पामा राम।

Visit Date:- 11/12/23

Name:- NIRAJ KUMAR

Signature:- Niraj Kumar