

Quality and Utility Assessment of Completed EPA's

District: Bhopur Project Title: Bhopur -WDC- /2021-22

Block: Arar Sadar Panchayat: Daulatpur Village: Daulatpur Beneficiary Name: Govind /a/

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4516	Structure: Handpump	25.35'46' 84'41'8"	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य स्थल पर कार्य की गुणवत्ता ठीक है, जो कि ग्रामिणों द्वारा चापाकल का उपयोग किया जा रहा है, और डिस्पल्ट होई पाया गया है।
आस-पास के ग्रामीण लोग घर कपा - खाना और स्नान करना है।

Visit Date:- 10/11/2023 (11:51)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh