

### Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: PMKSY 2.0 -WDC-III/2021-22

Block: Nabinagar , Panchayat: Khaturi Pandu , Village: Shivpur , Beneficiary Name: Dinesh Kumar Mehta

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18924	Structure: Hand Tubewell with Soak Pit	24.513625	100%	100 %	100%	100 %	100 %	100
		84.110033						

**Remark** (Overall Quality & Utility of Structure):

Structure की गुणवत्ता अच्छी है, लाभार्थी द्वारा उपयोग में है। structure के पास display board लगा हुआ है।

Visit Date:- 13.10.23

Name:- Shishupal

Sign:- Shishupal