

Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: PMKSY 2.0 -WDC- II/2021-22

Block: Deo , Panchayat: Bedhna , Village: Karamdih , Beneficiary Name: Dharmendra Bhuiyan

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18975	Structure: chabutra	24.603293 84.42022	100 %	100 %	100 %	80 %	80 %	92

Remark (Overall Quality & Utility of Structure):

Structure की गुणवत्ता अच्छी है, लोग द्वारा उपयोग में है। चबूत्रे में display board लगा हुआ है।

Visit Date:- 29.09.23

Name:- Shishupal

Sign:- Shishupal