

### Quality and Utility Assessment of Completed EPA's

District: BAN KA Project Title: BAN KA -WDC- II /2021-22

Block: Katoriya Panchayat: Harhar Village: Satiyari Beneficiary Name: Rajesh Kumar

| Work ID | Name/ description of activity        | Latitude & Longitude   | Work Identification<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Site Identification<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Specification<br>Followed<br>(Totally 100%,<br>Mostly 80%,<br>Average 60%,<br>Poor 40%) | Physical Appearance<br>of Structure<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Utility of Structure<br>(In full use 100%,<br>partially used 80%,<br>Yet to be used 70%,<br>Occasionally used 60%,<br>Not used/rarely used 40%) | Average<br>Score |
|---------|--------------------------------------|------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| 1       | 2                                    | 3                      | 4                                                                                 | 5                                                                                 | 6                                                                                       | 7                                                                                                 | 8                                                                                                                                               | 9                |
| 18871   | Structure:<br>Renovation of<br>Bandh | 24.787174<br>86.736606 | 100%                                                                              | 100%                                                                              | 100%                                                                                    | 100%                                                                                              | 100%                                                                                                                                            | 100%             |

**Remark** (Overall Quality & Utility of Structure):

कार्य-शाला का चयन एवं कार्य की गुणवत्ता ठीक है, जो कि ग्रामीणों द्वारा बाँध का उपयोग 'सिनेपस' इत्यादि में किया जाता है।

Visit Date:- 21/12/23

Name:- Brindaban Mahto Signature:- Brindaban