

Quality and Utility Assessment of Completed EPA's

District: Aunangabad , Project Title: PMKSY 2.0 -WDC- II/2021-22

Block: Madanbur , Panchayat: South Umga , Village: Umga tola , Beneficiary Name: Baudh Singh Bhogta

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18973	Structure: Hand Tubewell with soakpit	24.3418 84.3326	100%	100%	100%	100%	100%	100

Remark (Overall Quality & Utility of Structure):

Structure की जोरदार अच्छी है, लगेत के द्वारा उपयोग में है।
Display board लगा हुआ है।

visit date:- 01-06-2024

Name:- Shishupal

sign:- Shishupal